Parker's Packards
120 River Road
Rutland, MA 01543 USA
+17745780873
parkerspackards@gmail.com

Invoice

Parker's Packards
Est. 2002

BILL TO
Tom Laferriere
Laferriere Classic Cars
6 Lark Industrial Dr
Greenville, RI 02828

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
4290	02/23/2026	$1,529.95	02/23/2026	Due on receipt	

VEHICLE
1934 Packard 1101 5pass Coupe

DATE OF WORK
2/9/26 - 2/20/26

ACTIVITY	QTY	RATE	AMOUNT
Laferriere Classic Cars			
Parts Muffler hanger (my cost)	1	4.00	4.00T
Parts Wix oil filter (my cost)	1	15.00	15.00T
Parts Drain plug copper washer (my cost)	1	3.00	3.00T
Parts 30W Penn Grade oil (my cost)	8	6.75	54.00T
Parts NOS throw out bearing (my cost)	1	45.00	45.00T
Shipping S&H for throw out bearing	1	9.75	9.75
Parts Optima 6v battery (my cost)	1	234.50	234.50T
Shipping S&H for battery	1	11.99	11.99
Discount Friend discount %20, $283.50 see below	1	0.00	0.00
SUBTOTAL - Laferriere Classic Cars			377.24
Tom Laferriere:LA1934PAC			
Services 1934 Packard 1101 5 Pass Coupe: NOS throw out bearing arrived. Freed up and packed with new bearing grease. Pressed bearing onto throw out casting. Installed flywheel, clutch, pressure plate and re-install	13:30	0.00	0.00

ACTIVITY	QTY	RATE	AMOUNT
transmission. Reconnected cross member, Speedo cable, return springs. Shifter and floor boards installed. Carpet in with pedals mounted. (no charge)			
Services Test run vehicle with different battery to confirm that original battery is bad and causing volts to spike and overheat coils. With our shop battery in the car, the charging system is working properly, there is no spike in generator output (we were seeing 9.5v off idle). Order a new replacement battery. Install new tail pipe hanger to eliminate the rattle. Start vehicle to warm up oil. Drain oil, had to remove oil filter housing to separate. Housing kept spinning when trying to twist top off. Separated on bench to remove Wix oil filter. Replaced with new oil filter, and new oil drain plug copper washer. Filled with 8 quarts of 30wt oil. Fill all 4 shocks with hydraulic oil so that we can monitor how quickly they are leaking. All 4 shocks are noticeably wet. Remove old battery and install new Optima battery in battery box. Start car and observe charging output- charges at 7.2 volts, and doesn't climb beyond that. Strap down battery and re-install drivers seat. Preform a Pre-Delivery Inspection and cover car until arrangements can be made for pick-up.	10:30	135.00	1,417.50
SUBTOTAL - Tom Laferriere:LA1934PAC			1,417.50

Thank you for your business. Please note that there is a 30 day warranty period on parts and labor. Invoices over 30 days late incur an 18% finance charge.

SUBTOTAL	1,794.74
DISCOUNT	-283.50
TAX (6.25%)	18.71
TOTAL	1,529.95
BALANCE DUE	**$1,529.95**

Ways to pay

View and pay